

							Type of Violation		
		Treatment	Type of Wood	Charges Sampled	Charges Passed	Charges in Violation		Penetration	Retention
American Timber & Steel Co Inc, Norwalk, OH (0029V6)									
		CCA	Southern Pine	1	1	0		0	0
Compliance Rate:	100.0%			1	1	0		0	0
Commercial Lumber Sales, Inc, N Little Rock, AR (002978)									
		CCA	Southern Pine	2	2	0		0	0
		MCA	Southern Pine	11	8	3		0	3
Compliance Rate:	76.9%			13	10	3		0	3
Escue Wood Preserving Inc, Millwood, KY (002991)									
		uCA-C	Southern Pine	3	3	0		0	0
Compliance Rate:	100.0%			3	3	0		0	0
Forest Products Distributors Inc, Rapid City, SD (00298V)									
		CCA	Lodgepole Pine	1	1	0		0	0
		CCA	Ponderosa Pine	13	10	3		3	0
		CCA	Southern Pine	1	1	0		0	0
Compliance Rate:	80.0%			15	12	3		3	0
Great Southern Wood Preserving Inc, Buckner, MO (002986)									
		CCA	Southern Pine	1	1	0		0	0
		MCA	Southern Pine	71	60	11		0	11
Compliance Rate:	84.7%			72	61	11		0	11
Hatfield Lumber Co, Hatfield, AR (00297A)									
		CCA	Southern Pine	2	2	0		0	0
Compliance Rate:	100.0%			2	2	0		0	0
Hixson Lumber Sales, Plummerville, AR (00297G)									
		CCA	Southern Pine	1	1	0		0	0

							Type of Violation		
		Treatment	Type of Wood	Charges Sampled	Charges Passed	Charges in Violation		Penetration	Retention
		MCA	Southern Pine	48	40	8		1	7
Compliance Rate:	83.7%			49	41	8		1	7
Iowa Wood Preservers Inc, Oskaloosa, IA (002987)									
		CA-C	Southern Pine	3	3	0		0	0
Compliance Rate:	100.0%			3	3	0		0	0
Lumber One Wood Preserving LLC, Sheffield, AL (002988)									
		CA-B	Southern Pine	1	0	1		0	1
Compliance Rate:	0.0%			1	0	1		0	1
Midwest Manufacturing, Eau Claire, WI (002992)									
		MCA	Southern Pine	15	14	1		0	1
Compliance Rate:	93.3%			15	14	1		0	1
Mississippi Valley Forest Products, DICKEYVILLE, WI (002985)									
		Penta	Southern Pine	14	4	10		0	10
Compliance Rate:	28.6%			14	4	10		0	10
Scott Post Inc, Poplar Bluff, MO (002984)									
		Creosote	Southern Pine	5	5	0		0	0
Compliance Rate:	100.0%			5	5	0		0	0

							Type of Violation				
		Treatment	Type of Wood	Charges Sampled	Charges Passed	Charges in Violation		Penetration	Retention		
Sentinel Industries, Inc., Ashland, MO (00296Z)											
		CCA	Southern Pine	3	2	1		1	0		
Compliance Rate:	66.7%			3	2	1		1	0		
Southeast Wood Treating Inc (Georgia Pacific), Pleasant Hill, MO (00296W)											
		CA-C	Southern Pine	7	7	0		0	0		
		EL2	Southern Pine	49	47	2		1	1		
Compliance Rate:	96.4%			56	54	2		1	1		
Tri-State Lumber Co. Inc., Fulton, MS (002976)											
		CCA	Southern Pine	3	0	3		0	3		
Compliance Rate:	0.0%			3	0	3		0	3		
Universal Forest Products, Harrisonville, MO (00297W)											
		MCA	Southern Pine	58	57	1		0	1		
Compliance Rate:	98.3%			58	57	1		0	1		
			Overall Totals:	313	269	44		6	38		
			Service Samples:	1							
			Total Samples:	314							
			Overall Compliance:	85.9%							

**2014 Missouri Producer Inspections**

Arneson Timber Company, Steelville, MO	1
Great Southern Wood Preserving Inc, Buckner, MO	10
Houston Wood Treating Co, Houston, MO	1
Massie Pole Yard Inc, Van Buren, MO	1
Missouri Tie & Timber, Inc., Bunker, MO	1
Scott Post Inc, Poplar Bluff, MO	1
Southeast Wood Treating Inc (Georgia Pacific), Pleasant Hill, MO	11
Steelville Post & Lumber LLC, Steelville, MO	1
Stratman Lumber, MALDEN, MO	1
Universal Forest Products, Harrisonville, MO	10
<b>Total</b>	<b>38</b>

## 2014 Statistical Summary

Producer Licenses Issued	64
Dealer Licenses Issued	851
Number of Producer Inspections	39
Number of Dealer Inspections	138
Total Number of Inspections	177
Regulatory Samples	313
Service Samples	1
Compliance Samples	1
Total Samples	315
CA-B	1
CA-C	10
CCA	28
Creosote	5
EL2	50
MCA	203
Penta	15
uCA-C	3
Total Retention Tests Performed	298
Total Penetration Tests Performed In Field	300
Total Tests	598